

NO: LC-054 **PRODUCT:** F3SN Light Curtain Peripherals
DATE: December 2015 **TYPE:** Discontinuation Notice

F39-MC11 and F39-MT11 Peripherals for F3SN Safety Light Curtains to be Discontinued

Discontinuation date: March 2018

Reason for discontinuation: The F3SN safety light curtain family was discontinued in March 2012. Omron maintains stock of replacement parts for 7 years to support customer installations.

Affected Parts

Product discontinuation	Description	Recommended replacement
F39-MT11	Maintenance Tool for F3SN series Safety Light Curtains	No recommended replacement
F39-MC11	Setting Console for F3SN series Safety Light Curtains	

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.