

**End Of Life Notice**  
(Notification – P2205026-DI)  
May 31, 2022

**To:** *Our Valued Distribution Customer*

**Overview:** The purpose of this notification is to communicate Renesas Electronics America, Inc. (REA) has begun the End of Life (EOL) Process on select Support Tools.

**Affected Products:** A review of our records indicates the list of products in the appendix may affected your company.

Part numbers given in this list are for active part numbers in REA database at the time of this notification.

**Key Dates:**

Final last time buy ( <b>LTB</b> ) orders placed to REA or to a franchised REA distributor.	<b>Nov 15<sup>th</sup>, 2022</b>
Planned date for last time shipment ( <b>LTS</b> ) from REA.	<b>Feb. 15<sup>th</sup>, 2023</b>

**Response:** Please place last time buy (LTB) orders in a timely manner prior to the key dates listed to avoid product availability issues. If you anticipate volumes beyond your regular rate, please contact your REA sales representative with a forecast of your requirements. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas' General Terms and Conditions of Sale (<https://www.renesas.com/us/en/legal/terms-and-conditions.html>). Renesas will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please work with your REA sales representative and/or FAE to determine suitable replacement devices.

Please contact your REA sales representative for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics America, Inc.

### Appendix: Affected Part List

Booking Part Number	Replacement PN	Supported Device
QB-144GJ-EA-01S		Repair is not available; Supported device is V850
QB-144GJ-EA-03S		Repair is not available; Supported device is V850
R0C07800QSW01D	R0C07800QSW01N	Repair is not available; Supported device is RL78,78K
R0C07800QSW01D#L5	R0C07800QSW01N#L5	Repair is not available; Supported device is RL78,78K
R0C08500QSW01D	R0C08500QSW01N	Repair is not available; Supported device is V850
R0K564112S000BE		Repair is not available; Supported device is R32C/111
RTCRH8500CP01WDR	RTCRH8500CP01WNR	Repair is not available; Supported device is RH850
RTCRH8500CP01WDRN1	RTCRH8500CP01WNRN1	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR	RTCRH8500CS01WNR	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR L5	RTCRH8500CS01WNR L5	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR LA	RTCRH8500CS01WNR LA	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR LT	RTCRH8500CS01WNR LT	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR N1	RTCRH8500CS01WNR N1	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR N5	RTCRH8500CS01WNR N5	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR NA	RTCRH8500CS01WNR NA	Repair is not available; Supported device is RH850
RTCRH8500CS01WDR NT	RTCRH8500CS01WNR NT	Repair is not available; Supported device is RH850
RTCRL7800CN01WNRN1	RTCRL7800CS01WNRN1	Repair is not available; Supported device is RL78
RTCRX0000CS03WDR	RTCRX0000CS03WNR	Repair is not available; Supported device is RX
RTCRX0000CS03WDRN1	RTCRX0000CS03WNRN1	Repair is not available; Supported device is RX