## THALES

ID No. 921 Product/		Process	Change Notification	Date 10.10.2022	
Product			Ordering	g Code	
PLS62-W Rel.1			L30960N	4600A100	
Ordering Code changes:			Yes	⊠No	
Product		New Ordering Code			
Reason of Change:				☐ Change of production proce	ss/logistical changes
Customer requirement			Location of production moved		
Quality improvement				Other:	
	1				
Description of change:				about introduction of 2 <sup>nd</sup> source m W Rel.1 module.	emory for our
				oduct vendor announced PCN fro provide new MID (Manufacturer	
		chang custo	ge the origina mer's module	roduct's datasheet, this 2 <sup>nd</sup> mem al memory functions and performa e design will not be affected. Tha memory source successfully.	ances at all, and the
		modu	les will have	with this 2 <sup>nd</sup> memory source, the a minor adaption to identify the r ce the new FW to the above prod	new memory MID.
		The n	ew software	application string is:	
			SVN 05	Rev 02.013 ARN 01.000.15	
		The n	ew FW has I	been certified with GCF/PTCRB/	AT&T approvals.
		No re	gulatory certi	ification update required.	
				questions, our FAE team who of should be contacted.	fers comprehensive
Schedule details: CW/Y		CW/Y	ÆAR		
Availability of SW for evaluation:		CW41	1/2022		
Availability of modules ex THALES DIS AIS Deutschland warehouse:		CW48	3/2022		

## THALES

If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks,
THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

## Attachments:

10/13/2022 13.10.2022

X July

Product Program Manager Signed by: SUN Xiao-Lin X i. Voi duam

Head of Quality Management IoT Signed by: ERDMANN Joerg