

### 1 Products affected

Product hierarchy no. *				Part no. SBU Type / Description		Type / Description	Customer part no.
SBU	PG	PUG	Туре				
02	005	012	0000001150	4301.1214.03		FD2 fuse drawer 1P 10A	n/a
				4301.1401		FD2 fuse drawer 2P 10A	n/a
				4301.1403		FD2 fuse drawer 2P 10A	n/a
				4301.1409	Connectors	FD2 fuse drawer 2P 10A	n/a
				4301.1403.G	Connectors	FD2 fuse drawer 1P 10A	n/a
				4301.1405		FD2 fuse drawer 1P 10A	n/a
				4301.1407		FD2 fuse drawer 1P 10A	n/a
				4301.1411		FD2 fuse drawer 1P 10A	n/a


<sup>\*</sup>SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

Change country of origin

## 3 Detailed description of change

Change country of origin from Czechia (CZ) to Switzerland (CH)



# 4 Reason of change

Optimization of production process

### 5 Release date

Packaging

Packaging labels will be changed in week 26/2020 (Date code 2026 or higher on the label). This change has no effect on the validity of the approval certificates.

No change in packaging

### 6 Impact of change and recommended action

Form No No change in form

Fit No No change for dimension

Function No No change in function

Manufacturing No No change for manufacturing site

Label Yes Change of country of origin

#### 7 Reference Documents / Attachments

No

Kind of document	Remarks
Datasheet Fusedrawer 2	

Product CI	roduct Change Notification						Fusedrawer 2 change country of origin		
owner	creation date	release date	released by	change order no	rev	page	D40 046 502		
sariogar	22.06.2020	23.06.2020	muehlema	2020156	Α	1 of 1	D10-046-583		