

EFFECTIVE IMMEDIATELY

September 21, 2015

Dear Fluke Distributor:

The following distribution Products are being phased out effective immediately. Some of these products have a replacement model as shown on the table below. This letter is your notification of our product change.

PLEASE INFORM ALL RELEVANT PERSONNEL WITHIN YOUR ORGANIZATION.

Product Family	Obsolete Item Number	Obsolete Model	Obsolete Description	UPC	Replacement Item	Replacement Model	MSRP
FPQ	2654841	GPS430	GPS SYNC MODULE FOR FLUKE 430 SERIES	0 95969 35300 7	4693803	GPS430-II	
FPQ	3889483	3312-PR-TF	5000A FLUKE 1750 THIN FLEXI 122CM (48IN)	0 95969 57735 9	4531784	3312-PR-TF-II	
FPQ	3889476	3310-PR-TF	5000A FLUKE 1750 THIN FLEXI 61CM (24IN)	0 95969 57734 2	4531778	3310-PR-TF-II	

Stock Rotation Policy:

Fluke will allow distributors with inventory on-hand of the products affected by this notification to stock rotate the units until 10/21/15 if the conditions below are satisfied.

1. A new order equal to the minimum re-order or the return dollar amount, whichever is greater, is placed with Fluke at the time of return. Promotional orders or orders placed prior to the RMA request will not be considered as offsetting; and
2. Fluke has given prior approval for the return of such Products; and
3. The products were purchased no more than one (1) year before return date; and
4. Products are in new condition and in its original packaging.

Should you have any questions regarding this notice, please contact your Fluke Sales Manager.

Regards

Luis A. Katz
 Sr. NA Sales Operations Manager
 Fluke Corporation